N920PA, Diamond, DA-40, S/N 40.920, MT Propeller, MTV-12-B/183-59b, S/N 200861
1069.8 Tach, 1069.8 Total Time A/F
September 22, 2020

This new propeller, MTV-12-B/183-59b, S/N 200861, installed on Diamond A/C, DA-40, S/N 40-820. Installation done in accordance with Diamond Aircraft DA 40 Series Aircraft Maintenance Manual Doc# 6.02.01 and MT Propeller Manual E-124. Aircraft run up, checked propeller function, OK and checked for leaks, none found.

September 22, 2020, 1069.8 Tach, 1069.8 Total Time

Peter Vajsabel A&P 3477997 Peter Vajsabel A&P 3477997